

# Troubleshooting



## Restricted Dryer "Liquid Line"

SUCTION PSI: LOW

HEAD PSI: LOW

Indoor split will be bad.

Evaporator will be starved and not perform well.

